


NAT'L INST. OF STAND & TECH



A11107 210949



U. S. DEPARTMENT OF COMMERCE

BUILDING
MATERIALS
AND
STRUCTURES

REPORT BMS68

Performance Test of
Floor Coverings for Use in
Low-Cost Housing: Part 3

by

PERCY A. SIGLER
and ELMER A. KOERNER

NATIONAL
BUREAU OF STANDARDS



JUL 16 1943

54759

The program of research on building materials and structures, carried on by the National Bureau of Standards, was undertaken with the assistance of the Central Housing Committee, an informal organization of governmental agencies concerned with housing construction and finance, which is cooperating in the investigations through a committee of principal technicians.

CENTRAL HOUSING COMMITTEE
ON RESEARCH, DESIGN, AND CONSTRUCTION

A. C. SHIRE, *Chairman.*

United States Housing Authority.

HOWARD P. VERMILYA, *Vice Chairman.*

Federal Housing Administration.

STERLING R. MARCH, *Secretary.*

PIERRE BLOUKE,
Federal Home Loan Bank Board.

HUGH L. DRYDEN,
National Bureau of Standards.

LOUIS A. SIMON,
Public Buildings Administration.

LUTHER M. LEISENRING,
Construction Division (War).

EDWARD A. POYNTON,
Office of Indian Affairs.

JOHN S. DONOVAN,
Farm Security Administration.

GEORGE W. TRAYER,
Forest Service (F. P. Laboratory).

JOSEPH M. DALLAVALLE,
Public Health Service.

GEORGE E. KNOX,
Yards and Docks (Navy).

WILLIAM R. TALBOTT,
Veterans' Administration.

WALLACE ASHBY,
Bureau of Agricultural Chemistry and Engineering.

NATIONAL BUREAU OF STANDARDS
STAFF COMMITTEE ON ADMINISTRATION AND COORDINATION

HUGH L. DRYDEN, *Chairman.*
Mechanics and Sound.

PHAON H. BATES,
Clay and Silicate Products.

HOBART C. DICKINSON,
Heat and Power.

WARREN E. EMLEY,
Organic and Fibrous Materials.

GUSTAV E. F. LUNDELL,
Chemistry.

ADDAMS S. McALLISTER,
Codes and Specifications.

HENRY S. RAWDON,
Metallurgy.

The Forest Products Laboratory of the Forest Service is cooperating with both committees on investigations of wood constructions.

[For list of BMS publications and directions for purchasing, see cover page III]

UNITED STATES DEPARTMENT OF COMMERCE · Jesse H. Jones, Secretary

NATIONAL BUREAU OF STANDARDS · Lyman J. Briggs, Director

BUILDING MATERIALS *and* STRUCTURES

REPORT BMS68

Performance Test of Floor Coverings for Use in
Low-Cost Housing: Part 3

by

PERCY A. SIGLER

and ELMER A. KOERNER



ISSUED JANUARY 31, 1941

The National Bureau of Standards is a fact-finding organization; it does not "approve" any particular material or method of construction. The technical findings in this series of reports are to be construed accordingly.

UNITED STATES GOVERNMENT PRINTING OFFICE · WASHINGTON · 1941

FOR SALE BY THE SUPERINTENDENT OF DOCUMENTS, WASHINGTON, D. C. · PRICE 15 CENTS



Foreword

Various installations of floor coverings have been subjected to performance tests at the National Bureau of Standards as part of a research program on building materials suitable for low-cost house construction. Technical information of their relative ability to withstand service should be of aid to consumers and to installers in selecting floor coverings and methods of installation to meet various flooring problems.

This report presents the results of a test on a third series of 40 installations in the Bureau's floor-testing chamber, as a supplement to reports BMS34 and BMS43.

LYMAN J. BRIGGS, *Director.*

Performance Test of Floor Coverings for Use In Low-Cost Housing: Part 3

By PERCY A. SIGLER *and* ELMER A. KOERNER

CONTENTS

	Page		Page
Foreword.....	ii	V. Results.....	4
I. Introduction.....	1	VI. Summary.....	6
II. Floor-testing chamber and equipment.....	2	VII. Comments and conclusions.....	22
III. Test conditions and procedure.....	2	VIII. Selected references.....	23
IV. Description of test installations.....	4		

ABSTRACT

A performance test was conducted in the floor-testing chamber of the National Bureau of Standards on a third series of 40 test installations. Included in the test were linoleums in sheet and tile form, cork-composition tile, sheet rubber, rubber tile, asphalt tiles, fiber-board tiles, felt-base floor coverings having various wearing surfaces, three monolithic floors, and a number of wood floors. The bonding agents used included lignin pastes, cumar-resin cement, alumina cement-latex paste, rubber cements, various asphaltic adhesives, and nails. Installations were made on concrete, strip-wood, and plywood subfloors. Installations on strip-wood subfloors were made with underlays of dry and asphalt-saturated lining felts. Descriptions of the testing equipment and test installations are given. Results showing the relative depth of the depressions in the floor coverings during the test are presented in tables. Brief summaries of the manner in which the various test installations performed are given, and photographs of the test panels after 48,000 cycles of the testing equipment are shown.

I. INTRODUCTION

There are Federal specifications for a number of nontextile floor coverings which can be

used as a basis for securing good-quality merchandise of a particular type [1].¹ Comparable information on the different types is of direct and economic interest to the consumer in selecting a floor covering to meet his particular need. In order to provide technical information of this nature, studies of some of the important properties of floor coverings have been made at the National Bureau of Standards in connection with a general research program on building materials and structures.

One phase of these studies consisted of laboratory performance tests of various installations of floor coverings. Lack of information on such important factors as quality of merchandise, condition of subfloor, extent of maintenance, and magnitude of exposure make direct comparisons in service difficult. In these performance tests it was possible to control many of the factors affecting performance in service. However, it was not found possible to include all such factors. No attempt was made to ascertain the effects of finishing coats, maintenance, age, and atmospheric conditions.

This report presents the results of a performance test on a third series of 40 installations in the Bureau's floor-testing chamber. The results obtained on the two previous series of installations were published in reports BMS34

¹ Figures in brackets refer to the list of selected references at the end of this paper.

and BMS43 [2, 3]. Included in report BMS34 are the results of tests on several kinds of linoleum, felt-base floor coverings with various wearing surfaces, pressed fiberboard, and strip-wood floors of maple, white oak, and yellow pine. Report BMS43 contains the results of tests on battleship linoleum, rubber in sheet and tile form, felt-base floor coverings with different wearing surfaces, magnesium-oxychloride monolithic floors, a cement-latex monolithic floor, and asphalt tiles of various compositions. The only alteration in the equipment used in the three performance tests was the substitution of a rubber-tired truck wheel in the second and third tests for one of the two steel-rimmed truck wheels used in the first test.

In order to obtain results within a comparatively short time, a laboratory test must necessarily be accelerated and severe. The testing equipment was a modification of that previously used in a study of industrial-type floors [4]. The materials tested represented good-quality merchandise in their respective fields. The generous cooperation of various manufacturers in furnishing materials for test is gratefully acknowledged.

Other laboratory investigations have been conducted on various floor coverings and adhesives to determine their relative merits with respect to specific properties. The results obtained in some of these investigations have been published [5, 6].

II. FLOOR-TESTING CHAMBER AND EQUIPMENT

The floor-testing chamber contains a concrete circular track 4 ft wide, $8\frac{1}{2}$ in. thick, and approximately 40 ft in diameter, with a metal-shod concrete curb on each side. The circular track is divided into 20 test spaces by metal thresholds, the surfaces of which are 4 in. above the structural slab. Wood or concrete subfloors and the various floor coverings were installed in these test spaces. Two different installations, 3 ft long, were made in each test space.

Figures 1 and 2 show portions of the circular track and the testing equipment used in this performance test. The principal features of the equipment were a "walking wheel", *G*

(fig. 1), a platform truck, *A*, and two casters, *E* and *F* (fig. 2).

The equipment was propelled around the track at about 2 miles an hour by the walking wheel, which was 4 ft in diameter and carried a load of approximately 275 lb. The wheel was shod with eight wooden blocks, *H* (fig. 1), 6 by 13 by $1\frac{1}{2}$ in., which were covered with a cushioning layer of rubber $\frac{1}{4}$ in. thick and a wearing surface of leather $\frac{1}{4}$ in. thick. This arrangement produced a bumping and slipping action between the wheel and the floor coverings and imitated, to some extent, a walking action. During the second half of the test, No. 3 grit garnet cloth was placed over the eight leather-surfaced shoes in order to accelerate the abrasive action. The average slippage of the walking wheel during the test was approximately 1 percent.

The platform truck was equipped with two wheels of 12-in. diameter. The inner wheel, *B* (fig. 1), had a solid rubber tire, $2\frac{1}{2}$ in. wide, and carried a load of approximately 500 lb. The outer wheel had a slightly crowned steel rim, 3 in. wide, and carried a load of approximately 600 lb.

On the front of the truck were mounted two lever mechanisms, *C* (fig. 2). A swivel steel-wheel caster, *E*, of 2-in. diameter and $\frac{7}{8}$ -in. width, was attached to one of the levers and exerted a force of 20 lb normal to the floor. A steel-ball caster, *F*, of 1-in. diameter, was attached to the other lever and exerted a force of 10 lb normal to the floor. Helical springs, *D*, were used for applying the loads on the casters.

The number of cycles around the track made by the testing equipment was recorded by a counter, *R* (fig. 1), mounted at the side of the track and operated by an arm attached to the truck. A dial depth gage, *S* (fig. 2), was used to measure the depressions made in the floor coverings by the equipment. The depth gage had a span of 8 in. and was equipped with a flat-ended foot of $\frac{1}{8}$ -in. diameter. The foot exerted a pressure of 20 lb/in².

III. TEST CONDITIONS AND PROCEDURE

With a few exceptions, the concrete subfloors used in this performance test were the same




FIGURE 1.—Side view of testing equipment.




FIGURE 2.—Front view of testing equipment and depth gage.

subfloors used in the two previous tests. The concrete consisted of 1 part of cement, 3 parts of sand, and 4 parts of gravel, by weight. The surface of the concrete had a steel-troweled finish and was thoroughly cleaned before installing the new floor coverings. New wood subfloors were installed and consisted of either tongued-and-grooved strip flooring or plywood. The strip flooring was blind-nailed with 8d cut nails to four wooden sleepers spaced 12 in. on centers. The sleepers were approximately parallel to the direction of travel of the truck and were embedded in concrete. The plywood was face-nailed to the sleepers, at intervals of 6 in., with 6d barbed and rosin-coated box nails.

The floor coverings were installed during July and August of 1939. Atmospheric conditions in the testing chamber during the installations ranged from 55 to 75 percent in relative humidity and from 70° to 90° F in temperature. A setting-up period of at least 2 weeks was allowed before starting the test. The performance test was started on September 11, 1939, and was stopped on March 19, 1940, after 48,000 cycles of the testing equipment. Atmospheric conditions in the testing chamber during the test ranged from 50 to 75 percent in relative humidity and from 30° to 85° F in temperature. The floor coverings were swept at least once every 500 cycles of the equipment, so that any effect on the results of loose particles from other test floors was negligible.

The floor coverings were subjected to 50 cycles of the testing equipment, after which reference marks of white enamel were placed at intervals beside the paths made by the walking wheel and the two truck wheels. Initial depth measurements were recorded for use in determining the depth of compression and wear caused by the equipment. On each of the 40 installations, 5 measurements were taken along each of the three paths, making a total of 600 readings. These measurements were repeated at 4,000, 10,000, 20,000, 24,000, 30,000, 40,000, and 48,000 cycles of the equipment. During the first 24,000 cycles the eight shoes of the walking wheel were surfaced with strips of leather belting, 6 in. wide. During the second 24,000 cycles the leather-covered shoes were surfaced with strips of No. 3 grit garnet cloth,

6 in. wide, which were replaced with new strips every 2,000 cycles. At the end of the test the floors were washed with soap and water and then photographed. In taking the photographs, a spot light, with the rays at an angle of approximately 45 degrees with the surface of the track, was used as a source of light in order to more clearly show any fractures or blisters in the floor coverings.

IV. DESCRIPTION OF TEST INSTALLATIONS

The 40 test installations in this performance test involved 26 different floor coverings and 11 different adhesives. With a few exceptions, specimens of each floor covering were installed on both a concrete and a wood subfloor. An outline of the test installations is given in table 1.

V. RESULTS

The depths of the depressions in the floor coverings made by the two truck wheels and the walking wheel, at different stages of the performance test, are recorded in table 1.

In general, the rubber-tired truck wheel caused very little damage to the floor coverings and bonding agents. The steel-tired truck wheel, however, caused failures ranging from small fractures or blisters in some of the floor coverings to complete crushing or separation from the subfloor of others. Many of the floor coverings were indented to an appreciable degree by the action of the steel-tired truck wheel. For the same floor covering the depressions were much greater on a wood subfloor than on a concrete subfloor. This was due to the compression and permanent deformation of the wood subfloors and to the compression of the felt underlays where used.

The depressions in the floor coverings caused by 24,000 cycles of the walking wheel surfaced with leather appeared to result principally from compression rather than wear. With a few exceptions the depths of the depressions were small. The average amount each floor covering was worn by 24,000 cycles of the walking wheel surfaced with abrasive cloth is shown in table 2. The averages were computed from the differences in the depths of

TABLE 1.—Test installations and results of measurements for depth of compression and wear

Test panel ^a	Subfloor	Underlay	Bonding agent	Floor covering		Average depth of depression made by—					
				Type and description ^b	Nominal thickness	Rubber-tired truck wheel		Steel-tired truck wheel		Walking wheel	
						10,000 cycles	48,000 cycles	10,000 cycles	48,000 cycles	24,000 cycles	48,000 cycles
1L	Concrete	None	Resin cement, cumar resin.	Marbleized linoleum; marbleized pattern, white.	$\frac{1}{8}$ in.	0.000	0.000	0.000	0.000	0.000	0.010
2L	Strip wood ^c	Lining felt ^d	Lignin paste	do	$\frac{1}{8}$.002	.005	.008	.034	.005	.011
1R	Concrete	None	do	Marbleized linoleum; marbleized pattern, tan.	$\frac{1}{8}$.000	.000	.000	.002	.000	.001
2R	Strip wood ^c	Lining felt ^e	do	do	$\frac{1}{8}$.000	.000	.005	.017	.001	.032
3R	Concrete	None	do	Linoleum tile; marbleized pattern, mahogany; burlap backing.	$\frac{1}{8}$.000	.000	.000	.003	.000	.002
4R	Strip wood ^c	Lining felt ^e	do	do	$\frac{1}{8}$.000	.000	.005	.014	.001	.004
3L	Concrete	None	do	Cork-composition tile; plain pattern, gray; no fabric backing.	$\frac{1}{8}$.000	.000	.001	(^b)	.000	.001
4L	Strip wood ^c	Lining felt ^e	do	do	$\frac{1}{8}$.000	.000	.006	.018	.001	.002
5L	Concrete	None	Cut-back rubber cement.	Sheet rubber; marbleized pattern brown.	$\frac{1}{8}$.000	.000	.000	.000	.001	.005
5R	do	do	Rubber dispersion, soap type.	Rubber tile; marbleized pattern, gray.	$\frac{1}{8}$.000	.000	.000	.001	.000	.006
6L	do	do	Alumina cement-latex paste.	Jaspe linoleum; jaspe pattern, brown.	$\frac{3}{32}$.000	.000	.003	.009	.001	.006
6R	do	do	do	Felt base; printed pattern, lavender; wearing surface, enamel.	$\frac{5}{64}$.000	.000	.008	.021	.001	.009
7R	do	do	Lignin paste	Felt base; printed pattern, red; wearing surface, enamel.	$\frac{5}{64}$.000	.001	.006	.023	.000	.010
8L	Plywood ⁱ	do	do	do	$\frac{5}{64}$.001	.001	.011	.043	.002	.013
7L	Concrete	do	do	Felt base; mottled pattern, white; wearing surface, resin-treated cotton-linters sheet duplexed to felt backing.	$\frac{5}{64}$.000	.001	.003	.007	.001	.003
8R	Plywood ⁱ	do	do	do	$\frac{5}{64}$.000	.000	.010	.040	.002	.004
9L	Concrete	do	do	Felt-base tile; jaspe pattern, brown; wearing surface, cellulose nitrate composition.	$\frac{5}{64}$.001	.000	.005	.012	.002	.003
10L	Strip wood ^c	Lining felt ^j	do	do	$\frac{5}{64}$.004	.004	.015	.041	.006	.008
9R	Concrete	None	Cut-back rubber cement.	Felt-base tile; jaspe pattern, green; wearing surface, cellulose nitrate composition.	$\frac{5}{64}$.001	.001	.007	.016	.002	.004
10R	Strip wood ^c	do	Lignin paste	do	$\frac{7}{64}$.001	.001	.009	.030	.001	.004
11L	Concrete	do	Alumina cement-latex paste.	Asphalt tile; plain pattern, green; 1-minute indentation, 0.010 in. ^k	$\frac{1}{8}$.000	.000	.002	.025	.000	.018
11R	do	do	Asphalt emulsion, soap type.	do	$\frac{1}{8}$.000	.000	.005	.018	.000	.018
12L	Plywood ⁱ	do	Alumina cement-latex paste.	do	$\frac{1}{8}$.000	.000	.010	(^b)	.003	.024
12R	do	do	Asphalt emulsion, soap type.	do	$\frac{1}{8}$.002	.002	.012	.128	.003	.017
13L	Concrete ^l	do	do	Asphalt tile; plain pattern, green; 1-minute indentation, 0.012 in. ^k	$\frac{3}{16}$.000	.000	.004	.044	.001	.019
14L	Strip wood ^c	Lining felt ^e	do	do	$\frac{3}{16}$.001	.001	.006	.125	.001	.011
13R	Concrete ^l	None	do	Asphalt tile; plain pattern, red; 1-minute indentation, 0.010 in. ^k	$\frac{3}{16}$.001	.001	.004	.024	.002	.012
14R	Strip wood ^c	Lining felt ^e	do	do	$\frac{3}{16}$.000	.001	.007	.061	.001	.010
15L	Concrete	None	Cut-back asphalt	Asphalt-impregnated fiberboard tile; plain pattern, green and red.	$\frac{1}{4}$.003	.003	.018	.115	.005	.030
16R	Plywood ^m	do	do	do	$\frac{1}{4}$.008	.010	.016	(^b)	.003	.062
15R	Concrete ^l	do	do	Asphalt-impregnated fiberboard tile; plain pattern, dull black.	$\frac{1}{4}$.003	.003	.015	.066	.006	.039
16L	Wood sleepers.	do	Blind-nailed, 8d cut nails.	Strip Douglas fir; B and better grade, edge-grained, flat-back; density, 27 lb/ft ³ ^p	$2\frac{5}{32}$.000	.000	.011	.064	.001	.034
17L	Concrete ^l	do	Warm asphalt	White-oak unit-block; flat-grained, two metal splines on back.	$\frac{1}{2}$	(*)	*.001	(*)	*.025	(*)	*.005
18L	Strip wood ^c	Asphalt-laminated sheathing paper.	Blind-nailed, 4d casing nails.	Red-oak unit-block; flat-grained, two metal splines on back.	$\frac{1}{2}$	(*)	*.001	(*)	*.028	(*)	*.007
17R	Concrete ^l	None	Hot asphalt	Rock-elm plywood tile; 3-ply, tongued-and-grooved.	$\frac{1}{2}$	(*)	*.001	(*)	*.031	(*)	*.005

For footnotes, see end of table.

TABLE 1.—Test installations and results of measurements for depth of compression and wear—Continued

Test panel	Subfloor	Underlay	Bonding agent	Floor covering		Average depth of depression made by—					
				Type and description	Nominal thickness	Rubber-tired truck wheel		Steel-tired truck wheel		Walking wheel	
						10,000 cycles	48,000 cycles	10,000 cycles	48,000 cycles	24,000 cycles	48,000 cycles
18R	Strip wood ^c	¼-in. sisal-fiber mat, rubberized.	None	Rock-elm plywood tile; 3-ply, tiles joined together with metal dowel pins.	$\frac{3}{8}$ in.	in. (*)	in. *.003	in. (*)	in. *.017	in. (*)	in. *.011
19L	do ^c	None	Face-nailed, 6d box nails.	Douglas-fir plywood; 5-ply	$\frac{1}{2}$.000	.000	.015	.046	.001	.009
19R	do ^c	Asphalt - impregnated sheathing paper.	Floor covering as installed.	Magnesium-oxychloride composition reinforced with expanded metal; plain pattern, green; aggregate, granite dust; density, 118 lb/ft. ³ ; crushing strength, 9,400 lb/in. ²	$\frac{1}{2}$.001	.003	.003	.039	.002	.014
20R	Concrete ^u	None	do	Alumina cement-latex composition; plain pattern, dark gray; aggregate, ground cork and silica; density, 61 lb/ft. ³ ; crushing strength, 9,400 lb/in. ²	$\frac{1}{2}$.009	.013	.019	.037	.014	.040
20L	do ^u	do	do	1:2 cement-mortar topping; aggregate, Potomac-river sand; cement-water ratio, 2½; interval between placing and troweling, 3½ hr.; damp-cured for 6 days; density, 137 lb/ft. ³ ; crushing strength, 8,800 lb/in. ²	1	.000	.000	.002	.011	.001	.011

^a L=left half of panel; R=right half of panel (facing the panels from the inside of the circular track).

^b Color listed is the predominating color.

^c Edge-grained Douglas fir, 2½ in. thick, with a 2¾ in. face.

^d 1 lb/yd² dry lining felt bonded to subfloor with lignin paste.

^e 1½ lb/yd² asphalt-saturated lining felt bonded to subfloor with lignin paste.

^f Size of tile, 8¾ by 8¾ in.

^g Size of tile, 9 by 9 in.

^h Floor covering was too severely damaged to measure accurately.

ⁱ Douglas fir plywood, ¾ in. thick, 5-ply.

^j ¾ lb/yd² dry lining felt bonded to subfloor with lignin paste.

^k Method prescribed in Federal Specification SS-T-306, Tile; Asphalt.

^l Subfloor given a priming coat of cut-back asphalt primer.

^m Size of tile, 12 by 24 in.

ⁿ Douglas fir plywood, ½ in. thick, 5-ply.

^o Surface given one heavy coat of a sealer.

^p At 65-percent relative humidity and 72° F temperature.

^q Size of unit-block 10 by 10 in.

^r Surface had a factory-applied finish.

* Accuracy of depth-gage measurements was questionable due to slight warping or displacement of floor covering. Measurements reported were made with either a micrometer or a straight edge and feeler gage after removal of the floor covering.

^s Size of tile, 8½ by 17 in.

^u Surface had a broom finish.

compression and wear at 24,000 and 48,000 cycles given in table 1.

With a few exceptions the ball and roller casters caused very little damage to the floor coverings.

The accompanying photographs, figures 3 to 42, show the general condition of the floor coverings at the end of the test. The five paths shown in the photographs are, from left to right, those made by the rubber-tired truck wheel, the steel-ball caster, the walking wheel, the steel-wheel caster, and the steel-tired truck wheel. The small white dots in the photographs are the white-enamel reference marks.

VI. SUMMARY

Brief summaries of the manner in which the various test installations performed are herewith presented.

The ¼-in. marbleized linoleums, panels 1L, 2L, 1R, and 2R, showed very good performance, with the possible exception of panel 2L (see figs. 3, 4, 5, and 6). In panel 2L a dry lining felt was used over the strip-wood subfloor. The action of the steel-tired truck wheel caused the dry lining felt to laminate, resulting in an appreciable fracture of the linoleum (see figure 4). In panel 2R, where an asphalt-saturated

TABLE 2.—Average wear of floor coverings caused by 24,000 cycles of the "walking wheel" surfaced with abrasive cloth ^a

Floor covering ^b	Average depth of wear
	<i>in.</i>
Marbleized linoleum; 1/8 in.; white	0.008
Marbleized linoleum; 1/8 in.; tan	.001
Linoleum tile; 1/8 in.; mahogany	.002
Cork-composition tile; 1/8 in.; gray	.001
Sheet rubber; 1/8 in.; brown	.004
Rubber tile; 1/8 in.; gray	.006
Jaspe linoleum; 3/32 in.; brown	.005
Felt base; 5/64 in.; lavender; wearing surface, enamel	.008
Felt base; 5/64 in.; red; wearing surface, enamel	.010
Felt base; 5/64 in.; white; wearing surface, resin-treated cotton-linters sheet	.002
Felt-base tile; 5/64 in.; brown; wearing surface, cellulose nitrate composition	.001
Felt-base tile; 7/64 in.; green; wearing surface, cellulose nitrate composition	.002
Asphalt tile; 1/8 in.; green	.018
Asphalt tile; 3/16 in.; green	.014
Asphalt tile; 3/16 in.; red	.009
Asphalt-impregnated fiberboard tile; 1/4 in.; green and red	.042
Asphalt-impregnated fiberboard tile; 1/4 in.; dull black	.033
Strip Douglas fir; 2 5/32 in.; edge-grained	.033
White-oak unit-block; 1/2 in.; flat-grained	.005
Red-oak unit-block; 1/2 in.; flat-grained	.007
Rock-elm plywood tile; 1/2 in.; 3-ply	.005
Rock-elm plywood tile; 3/8 in.; 3-ply	.011
Douglas-fir plywood; 1/2 in.; 5-ply	.008
Magnesium-oxide composition; 1/2 in.; green	.012
Alumina cement-latex composition; 1/2 in.; gray	.026
1:2 cement-mortar topping; 1 in.	.010

^a The relative value of a floor covering should not be based entirely on resistance to wear. Other factors should also be considered, such as cost, indentation characteristics, ease of maintenance, adherence to subfloors, resistance to tear and fracture, etc.

^b See table 1 for detailed description.

lining felt was used, there was no evidence of separation in the felt and the steel-tired truck wheel caused only slight fracture of the linoleum (see figure 6). The tan marbleized linoleum showed better resistance to abrasion than the white marbleized linoleum (see table 2).

The 1/8-in. linoleum tile, panels 3R and 4R, gave very good performance, particularly with reference to abrasion (see figs. 7 and 8). On a concrete subfloor the tiles were fractured slightly by the steel-tired truck wheel.

The 1/8-in. cork-composition tile, panels 3L and 4L, showed good performance except under the action of the steel-tired truck wheel, which fractured the tiles considerably (see figs. 9 and 10). On a concrete subfloor, panel 3L, tiles along the path of the steel-tired truck wheel showed failure in bond and were fractured at an early stage of the test. They were replaced with new tiles at 1,240 cycles, which proved to be equally unsatisfactory. The tiles showed good resistance to abrasion.

The 1/8-in. sheet rubber and the 1/8-in. rubber tile used in this performance test were additional portions of samples used in a previous perform-

ance test [3]. These floor coverings on a concrete subfloor, panels 5L and 5R, gave very good performance. Along the path of the steel-tired truck wheel there were small welts in the floor coverings, caused by accumulations of the adhesives (see figs. 11 and 12). The sheet rubber showed slightly better resistance to abrasion than the rubber tile (see table 2 in this report and table 2 in report BMS43).

The jaspe linoleum, panel 6L, was an additional portion of a sample used in a previous performance test [2]. In the previous test, extensive failures in adhesion to the subfloors occurred at an early stage of the test and the linoleum was in unserviceable condition at the end of the test. In the present test, with a different adhesive, there was no evidence of failure in bond and the floor covering showed good performance (see fig. 13).

The felt-base floor coverings with a wearing surface of enamel, panels 6R, 7R, and 8L, gave fair performance considering the type of service for which they are designed. The floor coverings were in unserviceable condition at the end of the test (see figs. 14, 15, and 16). On a Douglas fir plywood subfloor, panel 8L, the steel-tired truck wheel caused considerable depression and fracture in the floor covering (see table 1 and fig. 16); otherwise the floor covering presented a more even surface than is usually obtained on a strip-wood subfloor. The enamel surfaces of the floor coverings were worn through in spots by the walking wheel in approximately 30,000 cycles, or 6,000 cycles after the wheel had been covered with abrasive cloth. The total depth of wear is shown in table 2.

The felt-base floor covering with a wearing surface consisting of a resin-treated cotton-linters sheet, panels 7L and 8R, withstood the test very well. Along the path of the steel-tired truck wheel there was some failure in adhesion to the concrete subfloor and slight fracture of the floor covering (see fig. 17). On a Douglas fir plywood subfloor, panel 8R, the steel-tired truck wheel caused appreciable depression and slight fracture in the floor covering (see table 1 and fig. 18). The wearing surface showed good resistance to abrasion.

The 5/64-in. and the 7/64-in. felt-base tiles with a wearing surface consisting of a cellulose nitrate composition, panels 9L, 10L, 9R, and 10R,



FIGURE 3.— $\frac{1}{8}$ -in. marbled linoleum on concrete subfloor (test panel 1L).




FIGURE 4.— $\frac{1}{8}$ -in. marbled linoleum on strip-wood subfloor (test panel 2L).




FIGURE 5.— $\frac{1}{8}$ -in. marbled linoleum on concrete subfloor (test panel 1R).




FIGURE 6.— $\frac{1}{8}$ -in. marbled linoleum on strip-wood subfloor (test panel 2R).




FIGURE 7.— $\frac{1}{8}$ -in. linoleum tile on concrete subfloor (test panel 3R).



FIGURE 8.— $\frac{1}{8}$ -in. linoleum tile on strip-wood subfloor (test panel 4R).



FIGURE 9.— $\frac{1}{8}$ -in. cork-composition tile on concrete subfloor (test panel 3L).




FIGURE 10.— $\frac{1}{8}$ -in. cork-composition tile on strip-wood subfloor (test panel 4L).



FIGURE 11.— $\frac{1}{8}$ -in. sheet rubber on concrete subfloor (test panel 5L).



FIGURE 12.— $\frac{1}{8}$ -in. rubber tile
on concrete subfloor (test panel
5R).



FIGURE 13.— $\frac{3}{32}$ -in. jasper lin-
oleum on concrete subfloor
(test panel 6L).




FIGURE 14.— $\frac{5}{64}$ -in. felt base,
enamel wearing surface, on
concrete subfloor (test panel
6R).



FIGURE 15.— $\frac{5}{64}$ -in. felt base,
enamel wearing surface, on
concrete subfloor (test panel
7R).




FIGURE 16.— $\frac{5}{64}$ -in. felt base,
enamel wearing surface, on
plywood subfloor (test panel
8L).




FIGURE 17.— $\frac{5}{64}$ -in. felt base,
resin treated cotton linters
sheet wearing surface, on
concrete subfloor (test panel
7L).




FIGURE 18.— $\frac{5}{64}$ -in. felt base, resin treated cotton linters sheet wearing surface, on plywood subfloor (test panel 8R).




FIGURE 19.— $\frac{5}{64}$ -in. felt-base tile, cellulose nitrate composition wearing surface, on concrete subfloor (test panel 9L).




FIGURE 20.— $\frac{5}{64}$ -in. felt-base tile, cellulose nitrate composition wearing surface, on strip-wood subfloor (test panel 10L).




FIGURE 21.— $\frac{7}{16}$ -in. felt-base tile, cellulose nitrate composition wearing surface, on concrete subfloor (test panel 9R).




FIGURE 22.— $\frac{7}{16}$ -in. felt-base tile, cellulose nitrate composition wearing surface, on strip-wood subfloor (test panel 10R).



FIGURE 23.— $\frac{1}{8}$ -in. asphalt tile on concrete subfloor (test panel 11L).



FIGURE 24.— $\frac{1}{8}$ -in. asphalt tile
on concrete subfloor (test
panel 11R).




FIGURE 25.— $\frac{1}{8}$ -in. asphalt tile
on plywood subfloor (test
panel 12L).




FIGURE 26.— $\frac{1}{8}$ -in. asphalt tile
on plywood subfloor (test
panel 12R).



FIGURE 27.— $\frac{3}{16}$ -in. asphalt tile
on concrete subfloor (test panel
13L).




FIGURE 28.— $\frac{3}{16}$ -in. asphalt tile
on strip-wood subfloor (test
panel 14L).




FIGURE 29.— $\frac{3}{16}$ -in. asphalt tile
on concrete subfloor (test panel
13R).




FIGURE 30.— $\frac{3}{16}$ -in. asphalt tile
on strip-wood subfloor (test
panel 14R).




FIGURE 31.— $\frac{1}{4}$ -in. asphalt-
impregnated fiberboard tile on
concrete subfloor (test panel
15L).




FIGURE 32.— $\frac{1}{4}$ -in. asphalt-
impregnated fiberboard tile on
plywood subfloor (test panel
16R).



FIGURE 33.— $\frac{1}{4}$ -in. asphalt-impregnated fiberboard tile on concrete subfloor (test panel 15R).



FIGURE 34.— $\frac{25}{32}$ -in. strip Douglas fir on wood sleepers (test panel 16L).



FIGURE 35.— $\frac{1}{2}$ -in. white-oak unit-block on concrete subfloor (test panel 17L).



FIGURE 36.— $\frac{1}{2}$ -in. red-oak unit-block on strip-wood subfloor (test panel 18L).




FIGURE 37.— $\frac{1}{2}$ -in. rock-elm plywood tile on concrete subfloor (test panel 17R).



FIGURE 38.— $\frac{3}{8}$ -in. rock-elm plywood tile on fiber mat and strip-wood subfloor (test panel 18R).




FIGURE 39.— $\frac{1}{2}$ -in. Douglas-fir plywood on strip-wood subfloor (test panel 19L).



FIGURE 40.— $\frac{1}{2}$ -in. magnesium-oxychloride composition on strip-wood subfloor (test panel 19R).



FIGURE 41.— $\frac{1}{2}$ -in. alumina cement-latex composition on concrete subfloor (test panel 20R).




FIGURE 42.—1-in. cement-mortar topping, 1:2 mix, on concrete subfloor (test panel 20L).

withstood the test very well, with the possible exception of panel 10L (see figs. 19, 20, 21, and 22). On a strip-wood subfloor with a dry lining felt, panel 10L, the steel-tired truck wheel caused separation in the lining felt and displaced some of the tiles (see fig. 20). On a strip-wood subfloor with no lining felt, panel 10R, the $\frac{3}{4}$ -in. tiles were moderately fractured by the steel-tired truck wheel (see fig. 22). Ridges caused by the strip-wood subfloor showed on the surface of the $\frac{3}{4}$ -in. tiles with no underlay whereas they did not show on the surface of the $\frac{3}{4}$ -in. tiles with a felt underlay (compare figs. 20 and 22). The wearing surface of the tiles showed good resistance to abrasion.

The $\frac{1}{8}$ -in. and the $\frac{3}{16}$ -in. asphalt tiles showed fair performance on a concrete subfloor (see figs. 23, 24, 27, and 29). They were pitted and worn to a moderate degree by the steel-tired truck wheel (see table 1). The $\frac{1}{8}$ -in. asphalt tiles on Douglas fir plywood subfloors with no underlay, panels 12L and 12R, showed fair performance except under the action of the steel-tired truck wheel, which crushed the tiles completely (see figs. 25 and 26). The $\frac{3}{16}$ -in. asphalt tiles on a strip-wood subfloor with an underlay of felt, panels 14L and 14R, did not stand up well in this test. The tiles were crushed by the steel-tired truck wheel and were fractured to an appreciable degree by the walking wheel (see figs. 28 and 30). In general, the asphalt tiles were worn to a moderate degree by the abrasive action of the walking wheel (see table 2).

The $\frac{1}{4}$ -in. asphalt-impregnated fiberboard tiles, panels 15L, 16R, and 15R, were in unserviceable condition at the end of the performance test. They were pitted and worn to a considerable degree by both the steel-tired truck wheel and the steel-wheel caster (see table 1 and figs. 31, 32, and 33). The painted surface of the tiles was worn through by the walking wheel in approximately 30,000 cycles, or 6,000 cycles after the application of the abrasive cloth. The total depth of wear is shown in table 2.

The strip Douglas fir, panel 16L, was in unsatisfactory condition at the end of the test. The flooring was indented and splintered to an appreciable degree by both the steel-tired truck wheel and the steel-wheel caster (see table 1 and fig. 34). The Douglas-fir strip flooring showed poor resistance to abrasion.

The white-oak and the red-oak unit-blocks, panels 17L and 18L, showed good performance. The unit-blocks were moderately compressed, and were fractured or splintered to a slight extent, by the steel-tired truck wheel (see table 1 and figs. 35 and 36). There was no evidence of failure in bond to the subfloors, although the individual strips in the unit-blocks showed a slight tendency to warp. The white-oak unit-blocks showed slightly better resistance to abrasion than the red-oak unit-blocks (see table 2).

The $\frac{1}{2}$ -in. and the $\frac{3}{8}$ -in. Rock-elm plywood tiles, panels 17R and 18R, were in good condition at the end of the test. The tiles were

moderately compressed by the steel-tired truck wheel (see table 1). There was no appreciable fracturing or splintering of the tiles (see figs. 37 and 38). The $\frac{1}{2}$ -in. tile showed better resistance to abrasion than the $\frac{3}{8}$ -in. tile (see table 2). The $\frac{1}{2}$ -in. tiles showed a slight tendency to warp, and they were not in complete contact with the concrete subfloor over the entire area of the test panel. The $\frac{3}{8}$ -in. tiles laid over a $\frac{1}{4}$ -in. rubberized sisal-fiber mat were held together very well by the metal dowel pins but were noisy when walked upon.

The $\frac{1}{2}$ -in. Douglas-fir plywood, panel 19L, remained in fair condition throughout most of the test, although at the end it was in unsatisfactory condition. The plywood was indented and splintered to an appreciable degree by both the steel-tired truck wheel and the steel-wheel easter (see table 1 and fig. 39). The splintered condition did not occur until near the end of the test. The Douglas-fir plywood showed fair resistance to abrasion (see table 2).

The $\frac{1}{2}$ -in. magnesium-oxychloride composition floor reinforced with expanded metal, panel 19R, did not show satisfactory performance on a strip-wood subfloor. The floor was pitted and worn appreciably by the steel-tired truck wheel (see table 1 and fig. 40). A fine crack developed in the floor along the entire path of the walking wheel (see fig. 40). The floor showed only fair resistance to abrasion (see table 2).

The $\frac{1}{2}$ -in. alumina cement-latex composition floor, panel 20R, showed unsatisfactory performance. The surface was depressed appreciably by the steel-tired truck wheel and was also depressed to a moderate degree by the rubber-tired truck wheel and the leather-shod walking wheel (see table 1 and fig. 41). There was no evidence of fracture in the floor and bond to the concrete subfloor was excellent. The floor

was worn to an appreciable degree by the abrasive action of the walking wheel (see table 2).

The 1-in. cement-mortar topping, panel 20L, showed good performance. The topping was pitted and worn to a slight degree by the steel-tired truck wheel (see table 1 and fig. 42). The fine cracks showing along the path of the walking wheel are due to internal shrinkage of the topping. The topping showed fair resistance to abrasion (see table 2).

VII. COMMENTS AND CONCLUSIONS

Physical properties of floor coverings which should be considered and which have a bearing on their performance and durability in service are resistance to abrasion, resistance to tear and fracture, indentation characteristics, dimensional changes with change in atmospheric conditions, and resistance to cleansing and finishing materials. Floor coverings should be allowed to come to a moisture and temperature equilibrium normal to the location before being installed in order to minimize the effect of dimensional changes after installation.

In order to obtain a satisfactory installation of a floor covering, a number of factors must be considered in addition to the physical properties essential to all floor coverings. A dry, even, rigid, and clean subfloor is necessary for most floor coverings. A subfloor should be thoroughly inspected for these requirements and appropriate alterations made where needed. New concrete subfloors should be allowed to dry thoroughly before installing a floor covering. Over a strip-wood subfloor an underlay of lining felt is beneficial to thin floor coverings. Dry lining felt can be readily removed from the subfloor whereas the removal of asphalt-saturated felt is difficult. Where traffic conditions are

severe, especially trucking, dry lining felt is likely to separate in itself. Asphalt-saturated lining felt is considered preferable under such conditions. Douglas-fir plywood used as a subfloor furnishes an even surface, which is especially desirable for thin floor coverings or those which fracture readily. Where traffic or loads are likely to be heavy, a subfloor of lower compressibility would be necessary.

Many types of floor coverings need to be bonded to a subfloor. A failure in the bond is very likely to result in pronounced failure in the floor covering. Failure of a bond may result from an unclean or wet condition of the subfloor, separation in an underlay, a faulty adhesive or method of installation, or from excessive dimensional changes of a floor covering with changes in relative humidity and temperature.

In interpreting the results of this and the two previous performance tests [2, 3], it should be realized that the tests were greatly accelerated and represent very severe service. In the selection of a floor covering and method of installation, the nature of the exposure to which the floor will be subjected, the desires of the occupant as to appearance and comfort, and the service per unit of total cost (initial and maintenance or renewal) are of importance. In this respect, some of the lower-cost floor coverings and methods of installation, even though less durable, may render economical and satisfactory service for some types of occupancy.

VIII. SELECTED REFERENCES ²

- [1] Federal specifications for floor coverings:

<i>Title</i>	<i>Symbol</i>	<i>Price</i>
Linoleum; battleship-----	LLL-L-351	5¢
Linoleum; plain, inlaid, and printed-----	LLL-L-361	5¢
Carpet; cork-----	LLL-C-96	5¢
Tile; cork-----	LLL-T-431	5¢
Tile; asphalt-----	SS-T-306	5¢
Tile; floor, rubber-----	ZZ-T-301	5¢
Floor-covering; rubber, sheet--	ZZ-F-461	5¢
Matting; rubber-----	ZZ-M-71	5¢

- [2] P. A. Sigler and E. A. Koerner, Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 1, NBS Building Materials and Structures Report BMS34 (1940). 10¢.
- [3] P. A. Sigler and E. A. Koerner, Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 2, NBS Building Materials and Structures Report BMS43 (1940). 10¢.
- [4] W. E. Emley and C. E. Hofer, *Test of floor coverings for post-office workrooms*, J. Research NBS 19, 567 (1937) RP1046. 10¢.
- [5] P. A. Sigler and Myrtle B. Woodward, Indentation and Recovery of Low-Cost Floor Coverings, NBS Building Materials and Structures Report BMS14 (1939). 10¢.
- [6] P. A. Sigler and R. I. Martens, Properties of Adhesives for Floor Coverings, NBS Building Materials and Structures Report BMS59 (1940). 10¢.

WASHINGTON, October 5, 1940.

² Articles may be purchased from the Superintendent of Documents, U. S. Government Printing Office, Washington, D. C., at the prices indicated.



BUILDING MATERIALS AND STRUCTURES REPORTS

On request, the Superintendent of Documents, U. S. Government Printing Office, Washington, D. C., will place your name on a special mailing list to receive notices of new reports in this series as soon as they are issued. There will be no charge for receiving such notices.

An alternative method is to deposit with the Superintendent of Documents the sum of \$5, with the request that the reports be sent to you as soon as issued, and that the cost thereof be charged against your deposit. This will provide for the mailing of the publications without delay. You will be notified when the amount of your deposit has become exhausted.

If 100 copies or more of any paper are ordered at one time, a discount of 25 percent is allowed.

Send all orders and remittances to the *Superintendent of Documents, U. S. Government Printing Office, Washington, D. C.*

The following publications in this series are available by purchase from the Superintendent of Documents at the prices indicated:

BMS1	Research on Building Materials and Structures for Use in Low-Cost Housing.....	10¢
BMS2	Methods of Determining the Structural Properties of Low-Cost House Constructions..	10¢
BMS3	Suitability of Fiber Insulating Lath as a Plaster Base.....	10¢
BMS4	Accelerated Aging of Fiber Building Boards.....	10¢
BMS5	Structural Properties of Six Masonry Wall Constructions.....	15¢
BMS6	Survey of Roofing Materials in the Southeastern States.....	15¢
BMS7	Water Permeability of Masonry Walls.....	10¢
BMS8	Methods of Investigation of Surface Treatment for Corrosion Protection of Steel.....	10¢
BMS9	Structural Properties of the Insulated Steel Construction Company's "Frameless-Steel" Constructions for Walls, Partitions, Floors, and Roofs.....	10¢
BMS10	Structural Properties of One of the "Keystone Beam Steel Floor" Constructions Sponsored by the H. H. Robertson Co.....	10¢
BMS11	Structural Properties of the Curren Fabrihome Corporation's "Fabrihome" Constructions for Walls and Partitions.....	10¢
BMS12	Structural Properties of "Steelox" Constructions for Walls, Partitions, Floors, and Roofs Sponsored by Steel Buildings, Inc.....	15¢
BMS13	Properties of Some Fiber Building Boards of Current Manufacture.....	10¢
BMS14	Indentation and Recovery of Low-Cost Floor Coverings.....	10¢
BMS15	Structural Properties of "Wheeling Long-Span Steel Floor" Construction Sponsored by Wheeling Corrugating Co.....	10¢
BMS16	Structural Properties of a "Tilecrete" Floor Construction Sponsored by Tilecrete Floors, Inc.....	10¢
BMS17	Sound Insulation of Wall and Floor Constructions.....	10¢
BMS18	Structural Properties of "Pre-Fab" Constructions for Walls, Partitions, and Floors Sponsored by the Harnischfeger Corporation.....	10¢
BMS19	Preparation and Revision of Building Codes.....	15¢
BMS20	Structural Properties of "Twachtman" Constructions for Walls and Floors Sponsored by Connecticut Pre-Cast Buildings Corporation.....	10¢
BMS21	Structural Properties of a Concrete-Block Cavity-Wall Construction Sponsored by the National Concrete Masonry Association.....	10¢
BMS22	Structural Properties of "Dun-Ti-Stone" Wall Construction Sponsored by the W. E. Dunn Manufacturing Co.....	10¢
BMS23	Structural Properties of a Brick Cavity-Wall Construction Sponsored by the Brick Manufacturers Association of New York, Inc.....	10¢
BMS24	Structural Properties of a Reinforced-Brick Wall Construction and a Brick-Tile Cavity-Wall Construction Sponsored by the Structural Clay Products Institute.....	10¢
BMS25	Structural Properties of Conventional Wood-Frame Constructions for Walls, Partitions, Floors, and Roofs.....	15¢
BMS26	Structural Properties of "Nelson Pre-Cast Concrete Foundation" Wall Construction Sponsored by the Nelson Cement Stone Co., Inc.....	10¢
BMS27	Structural Properties of "Bender Steel Home" Wall Construction Sponsored by The Bender Body Co.....	10¢
BMS28	Backflow Prevention in Over-Rim Water Supplies.....	10¢
BMS29	Survey of Roofing Materials in the Northeastern States.....	10¢
BMS30	Structural Properties of a Wood-Frame Wall Construction Sponsored by the Douglas Fir Plywood Association.....	10¢
BMS31	Structural Properties of "Insulite" Wall and "Insulite" Partition Constructions Sponsored by The Insulite Co.....	15¢
BMS32	Structural Properties of Two Brick-Concrete-Block Wall Constructions and a Concrete-Block Wall Construction Sponsored by the National Concrete Masonry Association..	10¢

[List continued on cover page iv]

BUILDING MATERIALS AND STRUCTURES REPORTS

[Continued from cover page III]

BMS33	Plastic Calking Materials.....	10¢
BMS34	Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 1.....	10¢
BMS35	Stability of Sheathing Papers as Determined by Accelerated Aging.....	10¢
BMS36	Structural Properties of Wood-Frame Wall, Partition, Floor, and Roof Constructions with "Red Stripe" Lath Sponsored by The Weston Paper and Manufacturing Co.....	10¢
BMS37	Structural Properties of "Palisade Homes" Constructions for Walls, Partitions, and Floors, Sponsored by Palisade Homes.....	10¢
BMS38	Structural Properties of Two "Dunstone" Wall Constructions Sponsored by the W. E. Dunn Manufacturing Co.....	10¢
BMS39	Structural Properties of a Wall Construction of "Pfeifer Units" Sponsored by the Wisconsin Units Co.....	10¢
BMS40	Structural Properties of a Wall Construction of "Knap Concrete Wall Units" Sponsored by Knap America, Inc.....	10¢
BMS41	Effect of Heating and Cooling on the Permeability of Masonry Walls.....	10¢
BMS42	Structural Properties of Wood-Frame Wall and Partition Constructions With "Celotex" Insulating Boards Sponsored by The Celotex Corporation.....	10¢
BMS43	Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 2.....	10¢
BMS44	Surface Treatment of Steel Prior to Painting.....	10¢
BMS45	Air Infiltration Through Windows.....	10¢
BMS46	Structural Properties of "Scot-Bilt" Prefabricated Sheet-Steel Constructions for Walls, Floors, and Roofs Sponsored by The Globe-Wernicke Co.....	10¢
BMS47	Structural Properties of Prefabricated Wood-Frame Constructions for Walls, Partitions, and Floors Sponsored by American Houses, Inc.....	10¢
BMS48	Structural Properties of "Precision-Built" Frame Wall and Partition Constructions Sponsored by the Homasote Co.....	10¢
BMS49	Metallic Roofing for Low-Cost House Construction.....	10¢
BMS50	Stability of Fiber Building Boards as Determined by Accelerated Aging.....	10¢
BMS51	Structural Properties of "Tilecrete Type A" Floor Construction Sponsored by the Tilecrete Corporation.....	10¢
BMS52	Effect of Ceiling Insulation on Summer Comfort.....	10¢
BMS53	Structural Properties of a Masonry Wall Construction of "Munlock Dry Wall Brick," Sponsored by the Munlock Engineering Co.....	10¢
BMS54	Effect of Soot on the Rating of an Oil-Fired Heating Boiler.....	10¢
BMS55	Effects of Wetting and Drying on the Permeability of Masonry Walls.....	10¢
BMS56	A Survey of Humidities in Residences.....	10¢
BMS57	Roofing in the United States: Results of a Questionnaire.....	10¢
BMS58	Strength of Soft-Soldered Joints in Copper Tubing.....	10¢
BMS59	Properties of Adhesives for Floor Coverings.....	10¢
BMS60	Strength, Absorption, and Resistance to Laboratory Freezing and Thawing of Building Bricks Produced in the United States.....	15¢
BMS61	Structural Properties of Two Nonreinforced Monolithic Concrete Wall Constructions.....	10¢
BMS62	Structural Properties of a Precast Joist Concrete Floor Construction Sponsored by the Portland Cement Association.....	10¢
BMS63	Moisture Condensation in Building Walls.....	10¢
BMS64	Solar Heating of Various Surfaces.....	10¢
BMS65	Methods of Estimating Loads in Plumbing Systems.....	10¢
BMS66	Plumbing Manual.....	20¢
BMS68	Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 3.....	15¢